



1120 Lincoln Street, Suite 801  
Denver, CO 80203

March 21, 2016

Jenna Keller  
Keller Law LLC  
P.O. Box 771222  
Steamboat Springs, CO 80477

Re: Final Resolution - Complaint 200438263  
Complainant: Margaret Ann and Gregory Sprenger  
NW Graylin D Sand Unit #4-W (API #075-05951)

Dear Ms. Keller,

The Colorado Oil and Gas Conservation Commission (COGCC) received the subject complaint filed via email on behalf of your clients, Mr. Gregory Sprenger and Ms. Margaret Ann Sprenger. The complaint was regarding weeds at NW Graylin D Sand Unit #4-W (API #075-05951). The subject complaint is documented in COGCC document number 200438263, which can be found on the "Complaints" page, off of our main website <http://cogcc.state.co.us/>. The COGCC investigated this complaint and documented the results in COGCC document number 200438725.

At the time that the complaint was filed, the operator of the locations, Benchmark Energy LLC (Benchmark) was already the subject of an ongoing investigation by the COGCC by which COGCC staff sought penalty enforcement action due to compliance violations and environmental impacts at several facilities.

The following actions were taken by COGCC staff to resolve conditions reported in the complaint, with some actions having been completed before receipt of the complaint:

- On 8/19/2015 COGCC Inspector Craig Quint conducted an inspection of the location and issued Field Inspection Report (FIR) # 680300246 with a comment directing the operator to maintain weeds at the wellhead (attached).
- Due to a perceived pattern of non-compliance and reporting violations at multiple locations, COGCC Staff pursued an Order Finding Violation (OFV) hearing against the operator;
- The OFV hearing was held on January 26, 2016 seeking penalty enforcement action against Benchmark for compliance issues and environmental impacts at several facilities. At the hearing the Commission ruled in favor of the relief recommended by staff, authorizing foreclosure on Benchmark's existing financial assurance and the use of funds from the Oil and Gas Conservation and Environmental Response Fund to address environmental impacts resulting from Benchmark's violations, after a thirty-day period granted to the operator to bring the facilities into compliance.



Ms. Keller  
March 21, 2016  
Page 2

- On February 3, 2016 COGCC Director Matthew Lepore issued notice that Benchmark's Certificate of Clearance had been revoked, thereby suspending Benchmark's authority to sell or transport produced hydrocarbons from any of its permitted wells and locations in Colorado.

Complaint number 200438263 has been formally closed with the issuance of COGCC Order 1V-564, which can be found on the "Regulation" page of the COGCC website.

The COGCC is currently in the process of recovering the financial assurance on file for Benchmark. Once the financial assurance is recovered, the COGCC will create a plan for the proper plugging and abandonment of the wells in addition to the reclamation of impacted locations. Locations will be prioritized based on actual and threatened impact as well as the availability of personnel and equipment. Reclamation efforts will be scheduled according to the priority assigned to each location

Please advise Mr. and Ms. Sprenger to feel free to contact the COGCC directly to discuss the reclamation schedule.

If you have questions regarding this complaint or the investigation, please contact me.

Sincerely,

A handwritten signature in blue ink that reads "Megan J. Adamczyk". The signature is written in a cursive, flowing style.

Megan Adamczyk, Complaint Specialist  
Phone: 888-235-1101  
Email: [dnr\\_cogcc.complaints@state.co.us](mailto:dnr_cogcc.complaints@state.co.us)

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

08/19/2015

Document Number:

680300246

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	219123	312155	SCHURE, KYM	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 10380Name of Operator: BENCHMARK ENERGY LLCAddress: PO BOX 8747City: PRATT State: KS Zip: 67124

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Nash, Jerry	(316) 218-8184	jerry@benchmarkenergy.us	All Inspections
Murphy, Julie		julie.murphy@state.co.us	

**Compliance Summary:**QtrQtr: SENW Sec: 12 Twp: 8N Range: 54W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
07/30/2015	680300165	TA	TA	ACTION REQUIRED			No
11/10/2014	667200641	TA	TA	ACTION REQUIRED			No
08/12/2014	667200362	TA	TA	ACTION REQUIRED			No
07/31/2014	667200342	TA	TA	ALLEGED VIOLATION			Yes
08/08/2013	664001190	TA	TA	SATISFACTORY			No
07/09/2012	663300288	TA	TA	ACTION REQUIRED			No
06/16/2011	200312773	MI	TA	SATISFACTORY			No
05/17/2010	200250543	RT	TA	SATISFACTORY			No
08/04/2009	200215924	RT	TA	SATISFACTORY			No
04/22/2008	200130652	RT	SI	SATISFACTORY			No
06/20/2007	200115804	RT	SI	SATISFACTORY		Pass	No
06/08/2006	200091672	MI	SI	SATISFACTORY		Pass	No
07/05/2005	200074139	RT	SI	SATISFACTORY		Pass	No
06/15/2004	200055913	RT		SATISFACTORY		Pass	No
04/02/2003	200037006	RT	SI	SATISFACTORY		Pass	No
07/18/2002	200028847	RT	SI	SATISFACTORY	P	Pass	No
07/26/2001	200018309	MI	SI	SATISFACTORY		Pass	No
08/04/2000	200008428	RT	SI	SATISFACTORY		Pass	No

**Inspector Comment:**

## Follow-up Inspection

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
219123	WELL	TA	04/26/2013	SI	075-05951	NW GRAYLIN D-SAND UNIT 4-W	TA	<input checked="" type="checkbox"/>

**Equipment:**Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location****Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY	Recently mowed		

**Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	Corrective action from Doc#680300165 have been performed.		

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Good Housekeeping:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WEEDS	SATISFACTORY	Maintain weeds at wellhead.		

**Spills:**

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Equipment:**

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Other	0	SATISFACTORY	No change in equipment		

**Venting:**

Yes/No	Comment

<b>Flaring:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 219123

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/A/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:Name: \_\_\_\_\_ Address: \_\_\_\_\_  
Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 219123 Type: WELL API Number: 075-05951 Status: TA Insp. Status: TA

**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

S/A/V: SATISFACTORY CA Date: \_\_\_\_\_

CA: \_\_\_\_\_

Comment: \_\_\_\_\_

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
 Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
 Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

Lat \_\_\_\_\_ Long \_\_\_\_\_  
 DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

Inspector Name: SCHURE, KYM

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

S/A/V: SATISFACTOR  
Y Corrective Date: \_\_\_\_\_

Comment: **Continue BMP's for stormwater runoff erosion control and maintenance**

CA: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680300290	Sign @ wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3666673">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3666673</a>
680300291	Dead man - marked	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3666674">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3666674</a>