

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/21/2016

Document Number:

682500525

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	434883	434883	Trujillo, Aaron	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 96155Name of Operator: WHITING OIL & GAS CORPORATIONAddress: 1700 BROADWAY STE 2300City: DENVER State: CO Zip: 80290

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Waggoner, Kyle		kyle.waggoner@whiting.com	All Inspections
,		cara.mezydlo@whiting.com	All Inspections

**Compliance Summary:**QtrQtr: NENE Sec: 21 Twp: 10N Range: 58W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
02/09/2016	682500417			AR	I		No

**Inspector Comment:**This report is in response to Sundry Doc #4010030601, addressing CAs from Inspection Doc #682500417.**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
441558	SPILL OR RELEASE	CL	04/20/2015		-	SPILL/RELEASE POINT	CL

**Equipment:**Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>16</u>	Separators: <u>8</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: <u>1</u>	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: <u>16</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: <u>2</u>	Fuel Tanks: _____

**Location****Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Inspector Name: Trujillo, Aaron

<b>Signs/Marker:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Emergency Contact Number (S/AR): \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

<b>Good Housekeeping:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Fencing:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

<b>Equipment:</b>				
Type:	#	Satisfactory/Action Required:		
Comment				
Corrective Action				Date:

<b>Venting:</b>	
Yes/No	
Comment	

<b>Flaring:</b>			
Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action	Date:

<b>Predrill</b>			
Location ID: 434883			
<b>Site Preparation:</b>			
Lease Road Adeq.: _____		Pads: _____	Soil Stockpile: _____
<b>S/AR:</b> _____			
Corrective Action: _____		Date: _____	CDP Num.: _____
<b>Form 2A COAs:</b>			
<b>S/AR:</b> _____	<b>Comment:</b> _____		
<b>CA:</b> _____	<b>Date:</b> _____		
<b>Wildlife BMPs:</b>			

BMP Type	Comment
Material Handling and Spill Prevention	<p>Spill Prevention Control and Countermeasures (SPCC) plans are in place to address any possible spill associated with oil and gas operations throughout the State of Colorado.</p> <ul style="list-style-type: none"> <li>• Materials and fluids will be stored in a neat and orderly fashion.</li> <li>• Waste will be collected regularly and disposed of at an offsite facility.</li> <li>• Prompt cleanup is required of spills to minimize waste materials entering the stormwater runoff.</li> <li>• Drip pans will be used during fueling and maintenance to contain spills or leaks.</li> <li>• Cleanup of trash and discarded material will be done at the end of the work day.</li> <li>• Cleanup will consist of monitoring the road, location and any other work areas.</li> <li>• Material to be cleaned up includes trash, scrap, and contaminated soil.</li> </ul>
Storm Water/Erosion Control	Stormwater management plans (SWMP) are in place to address construction, drilling and operations associated with oil and gas development throughout the State of Colorado. BMPs will be constructed as necessary to prevent stormwater from leaving the construction site. BMPs used will vary according to the location, and will remain until the pad is reclaimed.
General Housekeeping	Equipment was removed from interim portion of the north side of the location as per document number 682500417.
Storm Water/Erosion Control	Erosion on the north end of the location was mitigated as per document number 682500417

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

Comment: \_\_\_\_\_

**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 0 Type: \_\_\_\_\_ API Number: - Status: \_\_\_\_\_ Insp. Status: \_\_\_\_\_

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Inspector Name: Trujillo, Aaron

Corrective Action: _____		Date: _____	
Reportable: _____	GPS: Lat _____	Long _____	
Proximity to Surface Water: _____		Depth to Ground Water: _____	
<b><u>Water Well:</u></b>			
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	Lat _____ Long _____
<b><u>Field Parameters:</u></b>			
Sample Location: _____			
Emission Control Burner (ECB): _____			
Comment: _____			
Pilot: _____		Wildlife Protection Devices (fired vessels): _____	
<b><u>Reclamation - Storm Water - Pit</u></b>			
<b><u>Interim Reclamation:</u></b>			
Date Interim Reclamation Started: _____		Date Interim Reclamation Completed: _____	
Land Use: RANGELAND			
Comment: _____			
1003a. Waste and Debris removed? _____			
CM _____			
CA _____		CA Date _____	
Unused or unneeded equipment onsite? <u>Pass</u>			
CM <span style="color: red;">Equipment has been removed.</span>			
CA _____		CA Date _____	
Pit, cellars, rat holes and other bores closed? _____			
CM _____			
CA _____		CA Date _____	
Guy line anchors marked? _____			
CM _____			
CA _____		CA Date _____	
1003b. Area no longer in use? _____		Production areas stabilized ? _____	
1003c. Compacted areas have been cross ripped? _____			
1003d. Drilling pit closed? _____		Subsidence over on drill pit? _____	
Cuttings management: _____			
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____			
Production areas have been stabilized? _____		Segregated soils have been replaced? _____	
<b>RESTORATION AND REVEGETATION</b>			
<b><u>Cropland</u></b>			
Top soil replaced _____		Recontoured _____ Perennial forage re-established _____	
<b><u>Non-Cropland</u></b>			

Inspector Name: Trujillo, Aaron

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation In Process

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: SATISFACTOR  
Y

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

Pits: ☐ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
CAs from Inspection Doc #682500417 required operator to repair erosion and remove stored equipment from the location, and to submit a form 4 with documentation proving CAs had been addressed. Operator submitted Sundry Doc #4010030601 with photo documentation showing erosion on the north end of the location had been repaired, and equipment stored on the north end of the location had been removed.	trujilloam	03/21/2016
Doc #682500417 states "Interim portions on eastern and northern sides of location currently not vegetated. Location appears to have been active 05/2015 and likely had missed the 2015 growing season; Interim areas will need to be vegetated to meet reclamation requirements. Seeding activities are advised to be completed prior to April 15, 2016."	trujilloam	03/21/2016