

PIT INSPECTION FORM



DATE 10/21/86 OPERATOR PATRICK A. DOMINY FIELD LOBO
COUNTY WASH LEASE MILLER-REDISTIA LOCATION SESE 23-3N-S4W

CLASS _____ LEASE SIGN: well YES NO TANK ID: YES NO

TYPE OF OBSERVED WATER DISPOSAL:

EVAP. PITS TANKS/TRUCKED INJECTED* NOT DETERMINED NA
ESTIMATED WATER PRODUCTION _____ GPM * (34.3) = 5 BPD

SKIM TANK: SIZE 1250 GALS, METAL FIBERGLASS PLASTIC CEMENT
COVERED YES NO, OVERFLOW YES NO

PITS: SKIM PIT(S) None EVAPORATIVE PIT(S)
SIZE: * = SQFT 90 * 50 = SQFT
MATERIAL 135 * 50 = SQFT
SCREEN: YES NO 30 * 40 = SQFT
SCREEN COLLAPSED YES NO TOTAL = SQFT
FLAGS YES NO LINER MATERIAL: COMM. BENT. _____
OIL COVERED % SYNTHETIC _____
SAND NATIVE SOIL _____
OIL COVERED 5+ %
BREACHED YES NO

COMMENTS

Well signs OK
E Pit #2 BREACHED WATER FLOWS INTO A SERIES OF PONDS (6+) over
A 1/4 mi STRETCH. WATER CARRIES OIL SCUM AND DEPOSITS ALONG WATERWAYS
AND IN PONDS - YOU WOULDN'T BELIEVE IT. LOC. IN CREEK BOTTOM.

PIT PERMIT YES NO, LINER REQUIRED YES NO, TDS _____ ppm

REPORTED WATER PRODUCTION 200 BBLS/DAY LEASE NUMBER 52293

*INJECTION FACILITY: NAME _____ LOCATION _____

NOTICE SENT YES NO

DATE SENT _____

INSPECTOR IZ. VACLAVIK

5-1