



00657611

LEASE INSPECTION FORM

Date 5-29-89

Operator Patrick Doherty

Field Lobo

Lease Name & No. Miller-Redicess "A"

County Washington

Tank Battery No. 3N-54P23

Location Sec Sec 23-3N-54W
Legal Description

Type of Inspection _____

Water Inflow _____ 200 (Bbls. per Day)

RESULTS OF INSPECTION

(Est. Pit Dimensions, CVD, Lined, Oil on Surface, etc.)

Type of Tank

SKIM TANK 7' Dia 600 S.T.

PIT NO. 1 75 X 40 Not CVD, 15% oil CVD

PIT NO. 2 100 X 50 Not CVD, Water Clean

PIT NO. 3 _____

ADDITIONAL PITS _____

CONDITION OF LEASE (Describe - Oil CVD. or Sat. Gr., Any Leaking, Safety Conditions, Etc.)

Pits Not Lined

RECOMMENDED ACTION (If Required) _____

INSPECTOR James