

PIT INSPECTION FORM



00657618

DATE 6/17/87 OPERATOR PATRICK A. DOHENY FIELD LOBO
COUNTY WASH LEASE MILLER REDDESS A LOCATION 212 SE 23-3N-S4W
MILLER REDDESS
CLASS _____ LEASE SIGN: YES _____ NO TANK ID: YES _____ NO _____ NA

TYPE OF OBSERVED WATER DISPOSAL:

EVAP. PITS _____ TANKS/TRUCKED _____ INJECTED* _____ NOT DETERMINED _____ NA
ESTIMATED WATER PRODUCTION _____ GPM * (34.3) = N/A BPD

SKIM TANK: SIZE 100 GALS, _____ METAL _____ FIBERGLASS _____ PLASTIC CEMENT
COVERED YES _____ NO, OVERFLOW YES _____ NO

PITS:	SKIM PIT(S)	<u>Same</u>	EVAPORATIVE PIT(S)	<u>Same</u>
SIZE:	* =	SQFT	* =	SQFT
	MATERIAL		* =	SQFT
	SCREEN: _____ YES _____ NO		* =	SQFT
	SCREEN COLLAPSED _____ YES _____ NO		TOTAL =	SQFT
	FLAGS _____ YES _____ NO		LINER MATERIAL:	COMM. BENT. _____
	OIL COVERED _____ %			SYNTHETIC _____
				NATIVE SOIL <u>YES</u> _____
				NONE _____
			OIL COVERED	_____ %
			BREACHED	<u>YES</u> _____ NO

COMMENTS PITS SAME AS LAST VISIT - BREACHED - WATER
DITCHED TO SURFACE DRAINAGES

PIT PERMIT _____ YES _____ NO, LINER REQUIRED _____ YES _____ NO, TDS _____ ppm
REPORTED WATER PRODUCTION _____ BBLS/DAY LEASE NUMBER _____
*INJECTION FACILITY: NAME _____ LOCATION _____

NOTICE SENT YES _____ NO DATE SENT _____ INSPECTOR R. VACLAVIK

NIDES
D ANALYSIS

5-2