

Inspection Photos
3/22/16
Facility #105180
HORN SPRINGS CANYON FACILITY



Figure 1 – Looking west.



Figure 2 – Looking west.



Figure 3 – Looking north. Produced water tanks on east side of pit.



Figure 5 – East side of pit and produced water tanks.