

Inspection Photos
3/22/16
Facility #256521
ANTONIO 23-29



Figure 1 – Lease sign



Figure 2 – Wellhead and generator shed.



Figure 3 – Pit and flowline to pit (center of photo).



Figure 4 – Pit and flowline to pit.



Figure 5 – Water in lower pit.



Figure 6 – Flowline and pits.