

March 1, 2016

Mr. Bob Chesson
Environmental Protection Specialist, Northeast Region
Colorado Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801
Denver, CO 80203

Re: 2015 Annual Groundwater Monitoring Report
Jerke UP 8-7 Tank Battery
SENE Section 7 T4N R65W
Weld County, Colorado
Facility #: 323755
Spill Tracking #: 200437785
Remediation #: 9300

Dear Mr. Chesson,

On behalf of PDC Energy, Inc. (PDC), Tasman Geosciences, Inc. (Tasman) is submitting this 2015 Annual Groundwater Monitoring Report for quarterly groundwater monitoring activities conducted at the Jerke UP 8-7 tank battery (Site). This report documents the results of groundwater gauging, groundwater sampling, and remediation activities conducted at the Site during 2015. As per discussions with COGCC staff, PDC is providing this summary annual report to assist in updating the COGCC on the progress and status of this open remediation Site.

A historic release was discovered at the Site on November 6, 2013, during removal of the produced water vault. Following excavation and well installation activities, groundwater monitoring was initiated during the first quarter 2014. The monitoring well network at the Site consists of 9 temporary monitoring and remediation wells (BH01 - BH09), as shown in Figure 1. Historic groundwater monitoring results are presented in Table 1. Groundwater monitoring results for 2015 are summarized below.

Sampling Event	Wells Exceeding COGCC Standards	Maximum Benzene Concentration (µg/L)
1Q 2015	BH02, BH04	14
2Q 2015	None (BH04 not sampled)	<1.0
3Q 2015	BH04	80
4Q 2015	BH02, BH04	150

Tasman initiated enhanced fluid recovery (EFR) and air sparge (AS) events at the Site during the first quarter 2014. EFR/AS will remain the selected remediation strategy for this Site through the first quarter 2016. Following the completion of remediation activities, four additional quarters of compliance groundwater monitoring will be conducted to confirm that BTEX concentrations remain below applicable COGCC Table 910-1 groundwater standards.

Please contact me at (720) 409-8791 if you have any questions regarding this report.

Sincerely,



Christine Wasko
Project Manager
Tasman Geosciences, Inc.







DRAWN BY: ESS	Facility Diagram PDC Energy – DJ Basin Jerke UP 8-7 Tank Battery SENE S7 T4N R65W Weld County, CO	 6899 Pecos Street Unit C Denver, CO 80221	LEGEND - - - Excavation Extent  Excavation Groundwater Sample Location  Monitoring Well Location  Point of Release  Groundwater Flow Direction	FIGURE 1 GROUNDWATER MONITORING SITE MAP
DATE: 2/2/2016			All locations are approximate unless otherwise noted	

TABLE 1
JERKE UP 8-7 TANK BATTERY
GROUNDWATER ANALYTICAL RESULTS SUMMARY TABLE

Sample ID	Date Sampled	Benzene (µg/L)	Toluene (µg/L)	Ethylbenzene (µg/L)	Total Xylenes (µg/L)	Depth to Water ⁽²⁾ (feet)
COGCC Table 910-1 Groundwater Standard (µg/L) ⁽¹⁾		5	560	700	1,400	
GW01	11/12/2013	230	370	160	2,200	~ 5
BH01	1/10/2014	270	2,300	390	5,800	7.41
BH01	4/29/2014	19	130	160	3,100	7.52
BH01	7/29/2014	4.3	<1.0	54	450	5.12
BH01	10/27/2014	1.6	<1.0	9.0	43	4.80
BH01	1/22/2015	2.2	2.4	73.0	690	6.92
BH01	4/20/2015	<1.0	<1.0	<1.0	<1.0	7.49
BH01	7/27/2015	<1.0	<1.0	<1.0	<1.0	4.02
BH01	10/6/2015	1.6	<1.0	56	280	4.67
BH02	1/10/2014	920	4.8	54	2,300	6.98
BH02	4/29/2014	180	<1.0	67	370	7.13
BH02	7/29/2014	27	<1.0	8.0	49	5.07
BH02	10/27/2014	65	<1.0	20	140	4.42
BH02	1/22/2015	14	<1.0	8.8	65	6.20
BH02	4/20/2015	<1.0	<1.0	<1.0	13	5.44
BH02	7/27/2015	1.5	<1.0	1.0	8.3	4.42
BH02	10/6/2015	19	<1.0	1.8	13	4.74
BH03	1/10/2014	1.1	1.1	15	240	7.08
BH03	4/29/2014	<1.0	<1.0	2.0	22	7.37
BH03	7/29/2014	<1.0	<1.0	<1.0	3.9	4.59
BH03	10/27/2014	<1.0	<1.0	<1.0	<1.0	4.42
BH03	1/22/2015	<1.0	<1.0	<1.0	<1.0	6.58
BH03	4/20/2015	<1.0	<1.0	<1.0	<1.0	7.14
BH03	7/27/2015	<1.0	<1.0	<1.0	<1.0	4.00
BH03	10/6/2015	<1.0	<1.0	<1.0	<1.0	4.53
BH04	1/10/2014	12,000	7,600	940	14,000	4.35
BH04	4/29/2014	150	1.4	33	330	4.64
BH04	7/29/2014	110	4.0	4.8	31	2.03
BH04	10/27/2014	NS	NS	NS	NS	NM
BH04	1/22/2015	9.5	<1.0	24	320	6.63
BH04	4/20/2015	NS	NS	NS	NS	7.09
BH04	7/27/2015	80	<1.0	11	270	4.04
BH04	10/6/2015	150	<1.0	5.8	6.2	4.65

TABLE 1
JERKE UP 8-7 TANK BATTERY
GROUNDWATER ANALYTICAL RESULTS SUMMARY TABLE

Sample ID	Date Sampled	Benzene (µg/L)	Toluene (µg/L)	Ethylbenzene (µg/L)	Total Xylenes (µg/L)	Depth to Water ⁽²⁾ (feet)
COGCC Table 910-1 Groundwater Standard (µg/L) ⁽¹⁾		5	560	700	1,400	
BH05	1/10/2014	1,800	240	230	3,100	4.13
BH05	4/29/2014	1.8	<1.0	<1.0	<1.0	4.47
BH05	7/29/2014	<1.0	<1.0	<1.0	<1.0	1.65
BH05	10/27/2014	5.6	<1.0	<1.0	<1.0	1.52
BH05	1/22/2015	<1.0	<1.0	<1.0	<1.0	3.80
BH05	4/20/2015	<1.0	<1.0	<1.0	<1.0	4.41
BH05	7/27/2015	<1.0	<1.0	<1.0	<1.0	1.30
BH05	10/6/2015	<1.0	<1.0	<1.0	<1.0	1.83
BH06	1/10/2014	<1.0	<1.0	<1.0	<1.0	4.63
BH06	4/29/2014	<1.0	<1.0	<1.0	<1.0	4.66
BH06	7/29/2014	1.3	<1.0	<1.0	<1.0	2.07
BH06	10/27/2014	<1.0	<1.0	<1.0	<1.0	1.95
BH06	1/22/2015	<1.0	<1.0	<1.0	<1.0	3.83
BH06	4/20/2015	<1.0	<1.0	<1.0	<1.0	4.46
BH06	7/27/2015	<1.0	<1.0	<1.0	<1.0	1.35
BH06	10/6/2015	2.2	<1.0	<1.0	<1.0	1.84
BH07	4/29/2014	<1.0	<1.0	<1.0	<1.0	5.51
BH07	7/29/2014	<1.0	<1.0	<1.0	<1.0	2.90
BH07	10/27/2014	<1.0	<1.0	<1.0	<1.0	2.73
BH07	1/22/2015	<1.0	<1.0	<1.0	<1.0	4.63
BH07	4/20/2015	<1.0	<1.0	<1.0	<1.0	5.44
BH07	7/27/2015	<1.0	<1.0	<1.0	<1.0	2.36
BH07	10/6/2015	<1.0	<1.0	<1.0	<1.0	2.83
BH08	4/29/2014	<1.0	<1.0	<1.0	<1.0	7.38
BH08	7/29/2014	<1.0	<1.0	<1.0	<1.0	3.78
BH08	10/27/2014	<1.0	<1.0	<1.0	<1.0	3.04
BH08	1/22/2015	<1.0	<1.0	<1.0	<1.0	5.51
BH08	4/20/2015	<1.0	<1.0	<1.0	<1.0	6.31
BH08	7/27/2015	<1.0	<1.0	<1.0	<1.0	3.24
BH08	10/6/2015	<1.0	<1.0	<1.0	<1.0	3.71

TABLE 1
JERKE UP 8-7 TANK BATTERY
GROUNDWATER ANALYTICAL RESULTS SUMMARY TABLE

Sample ID	Date Sampled	Benzene (µg/L)	Toluene (µg/L)	Ethylbenzene (µg/L)	Total Xylenes (µg/L)	Depth to Water ⁽²⁾ (feet)
COGCC Table 910-1 Groundwater Standard (µg/L) ⁽¹⁾		5	560	700	1,400	
BH09	4/29/2014	<1.0	<1.0	<1.0	<1.0	4.59
BH09	7/29/2014	<1.0	<1.0	<1.0	<1.0	2.00
BH09	10/27/2014	<1.0	<1.0	<1.0	<1.0	1.85
BH09	1/22/2015	<1.0	<1.0	<1.0	<1.0	3.76
BH09	4/20/2015	<1.0	<1.0	<1.0	<1.0	4.53
BH09	7/27/2015	<1.0	<1.0	<1.0	<1.0	1.43
BH09	10/6/2015	<1.0	<1.0	<1.0	<1.0	2.01

Notes:

1. Groundwater standards referenced from 2 CCR 404-1, Table 910-1, effective January 30, 2015.

COGCC = Colorado Oil and Gas Conservation Commission

2. Depth to water measured from top of well casing or ground surface for monitoring well samples and excavation samples, respectively.

µg/L = Micrograms per liter

(<) = Analytical result is less than the indicated laboratory reporting limit.

NS = Not sampled

NM = Not measured

BOLD = Analytical result is in exceedance of COGCC groundwater standards.