

Construction Inspection



Photo 1. Photo taken from entrance of location, facing East. Sediment control (silt fence) installed around perimeter of location.

Construction Inspection



Photo 2. Photo taken from southeast location, facing North along topsoil stockpile.

Construction Inspection



Photo 3. Photo taken from southeast location, facing North. Sediment control (silt fence) installed around perimeter of location.

Construction Inspection



Photo 4. Photo taken from eastern location, facing North. Sediment control (silt fence) installed around perimeter of location. Need to inspect and maintain silt fence frequently.

Construction Inspection



Photo 5. Photo taken from northeast location, facing West. Sediment control (silt fence) installed around perimeter of location.

Construction Inspection



Photo 6. Photo taken from northern location, facing North. Stormwater and sediment control (sediment trap) installed at location low-point.

Construction Inspection



Photo 7. Photo taken from northern location, facing South. Stormwater and sediment control (sediment trap) installed at location low-point.

Construction Inspection



Photo 8. Photo taken from northwest location, facing South. Sediment control (silt fence) installed around perimeter of location.

Construction Inspection



Photo 9. Photo taken from entrance of location, facing Northeast. Vehicle tracking pad installed to minimize sediment leaving location.