



Photo#1: View over Well Head to East

Photo#2:

Well Head is open to livestock Activity



Photo#3:





Photo#4:

Facilities have been removed, but Flow lines/Pipes/Valves remain



Photo#5:



Photo#6:

Equipment, Debris on Location



Photo#7:

