

Grynberg State 3-36

Inspection# 673403104

No capacity on tank label. No battery sign.



Gauge hatch open.



Low spots in berm.

