

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/28/2016

Document Number:

680600532

Overall Inspection:

SATISFACTORY w/ CMT
or AR**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	216323	326370	ROY, CATHERINE	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: 382 CR 3100City: AZTEC State: NM Zip: 87410

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Hixon, Logan	(505) 386-8018	logan_hixon@xtoenergy.com	
Trobaugh, Robert	505-333-3185	robert_trobaugh@xtoenergy.com	All Inspections
Harrison, Lyndon		lyndon_harrison@xtoenergy.com	

Compliance Summary:QtrQtr: NWNE Sec: 6 Twp: 34N Range: 8W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
06/23/2015	674602011	PR	PR	SATISFACTORY	I		No
03/11/2015	674601529	PR	PR	ACTION REQUIRED	I		No
09/12/2013	663401186	PR	PR	SATISFACTORY	P		No
08/12/2010	200267396	PR	PR	SATISFACTORY			No
06/20/2006	200099665	PR	PR	SATISFACTORY		Pass	No
06/28/2004	200058346	PR	PR	SATISFACTORY		Pass	Yes
09/11/2002	200032142	PR	PR	SATISFACTORY		Pass	No
12/12/2001	200023305	PR	PR	SATISFACTORY		Pass	No
11/08/2000	200012112	PR	PR	SATISFACTORY		Pass	No
09/14/1999	500150510	PR	PR			Pass	No
11/10/1997	500150509	PR	PR			Pass	No
10/18/1996	500150508	PR	PR			Pass	No
10/16/1995	500150507	PR	PR				No

Inspector Comment:

This is an interim reclamation and stormwater inspection. Any corrective actions not addressed from previous inspections are still applicable.

Related Facilities:

Inspector Name: ROY, CATHERINE

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
216323	WELL	PR	05/20/1993	GW	067-07929	SHIELDS 2-6	RI	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Emergency Contact Number (S/AR): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:

Type:	#	Satisfactory/Action Required:	
Comment			
Corrective Action			Date: _____

Venting:

Yes/No	
Comment	

Flaring:

Type	Satisfactory/Action Required	
Comment:		
Corrective Action:		Correct Action Date:

Predrill

Location ID: 216323

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Comment:** _____**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 216323 Type: WELL API Number: 067-07929 Status: PR Insp. Status: RI

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Inspector Name: ROY, CATHERINE

Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Location is adjacent to irrigated pastures and an irrigation ditch. Revegetation is progressing with dense grasses growing within the interim reclamation area. See attached photos.

1003a. Waste and Debris removed? _____

CM What appears to be irrigation pipe is being stored within the northern and eastern portions of the interim reclamation area. If this area is planned to be long-term storage for surface owner materials an interim reclamation waiver will be needed.

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass

CM _____
CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____
CA _____ CA Date _____

Guy line anchors marked? _____

CM _____
CA _____ CA Date _____

1003b. Area no longer in use? In Production areas stabilized ? In

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In

Production areas have been stabilized? In Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established In

Inspector Name: ROY, CATHERINE

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ I _____

Comment: _____

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: SATISFACTOR
Y

Corrective Date: _____

Comment: Stormwater erosion is controlled on the location at this time.

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
680600533	Inspection Photos	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3825779