

Interim Reclamation Inspection

4/5/2016

Operator: Noble

Location ID: 437743

Weld County, CO

SWSE Section 1 T9N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



04.05.2016 14:36

Figure 1: Photo taken from the southwest end of the location, facing east. Photo shows interim reclamation in process, and project area.



04.05.2016 14:36

Figure 2: Photo taken from the southwest end of the location, facing northeast. Photo shows interim reclamation in process, and project area.



04.05.2016 14:36

Figure 3: Photo taken from the southwest end of the location, facing north. Photo shows interim reclamation in process, and project area.



04.05.2016 14:37

Figure 4: Photo taken from the northwest corner of the project area, facing southeast. Photo shows wood beams stored on location.



Figure 5: Photo taken from the northern interim area. Photo shows evidence of germination.



Figure 6: Photo taken from the southeast corner of the location, facing southeast. Photo shows weed debris piled in the corner of the location.



Figure 7: Photo taken from the northeast corner of the location, facing west. Photo shows interim reclamation in process, and project area.



04.05.2016 14:40

Figure 8: Photo taken from the northeast corner of the location, facing southwest. Photo shows interim reclamation in process, and project area.



Figure 9: Photo taken from the northeast corner of the location, facing south. Photo shows interim reclamation in process, and project area.