

**FORM
INSP**

Rev
05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/05/2016

Document Number:

682500616

Overall Inspection:

SATISFACTORY w/ CMT
or AR

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>437743</u>	<u>437743</u>	<u>Trujillo, Aaron</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>100322</u>
Name of Operator:	<u>NOBLE ENERGY INC</u>
Address:	<u>1625 BROADWAY STE 2200</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Compliance Summary:

QtrQtr: SWSE Sec: 1 Twp: 9N Range: 58W

Inspector Comment:

This is an interim reclamation and stormwater inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
437716	WELL	AL	08/12/2014	LO	123-39647	McCaffrey State LD12-75-1AHN	AL	<input type="checkbox"/>
437719	WELL	PR	05/01/2015	OW	123-39649	Elway State LD01-74-1AHN	RI	<input checked="" type="checkbox"/>
437724	WELL	PR	05/01/2015	OW	123-39652	Elway State LD01-75-1BHN	RI	<input checked="" type="checkbox"/>
437727	WELL	PR	05/15/2015	OW	123-39654	McCaffrey State LD12-75-1BHN	RI	<input checked="" type="checkbox"/>
437745	WELL	AL	08/12/2014	LO	123-39662	McCaffrey State LD12-76-1BHN	AL	<input type="checkbox"/>
437746	WELL	PR	05/15/2015	OW	123-39663	McCaffrey State LD12-75HN	RI	<input checked="" type="checkbox"/>
437757	WELL	AL	08/12/2014	LO	123-39670	McCaffrey State LD12-74HN	AL	<input type="checkbox"/>
437759	WELL	PR	05/15/2015	OW	123-39672	McCaffrey State LD12-74-1AHN	RI	<input checked="" type="checkbox"/>
437761	WELL	AL	08/12/2014	LO	123-39673	Elway State LD01-76-1BHN	AL	<input type="checkbox"/>
437775	WELL	AL	08/12/2014	LO	123-39685	Elway State LD01-74HN	AL	<input type="checkbox"/>
437777	WELL	PR	05/01/2015	OW	123-39686	Elway State LD01-75HN	RI	<input checked="" type="checkbox"/>

437778	WELL	AL	08/12/2014	LO	123-39687	Elway State LD01-75-1AHN	AL	<input type="checkbox"/>
--------	------	----	------------	----	-----------	--------------------------	----	--------------------------

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>6</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: <u>6</u>
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Emergency Contact Number (S/AR): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
STORAGE OF SUPL	ACTION REQUIRED	What appears to be wooden 2x4 beams stored on location. Refer to figure 4 in the attached document.	This is unneeded equipment or trash debris and needs to be removed and properly stored or disposed.	04/17/2016

Spills:

Type	Area	Volume	Corrective action	CA Date

Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:

Type:	#	Satisfactory/Action Required:	
Comment			
Corrective Action		Date:	

Venting:

Yes/No	
--------	--

Comment	
---------	--

Flaring:

Type	Satisfactory/Action Required
Comment:	
Corrective Action:	Correct Action Date:

Predrill

Location ID: 437743

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Group	User	Comment	Date
OGLA	andrewsd	Reference Area Pictures taken during the 2014 growing season shall be submitted via a Form 4 Sundry Notice by 12/31/14.	06/10/2014

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

BMP Type	Comment
Storm Water/Erosion Control	Stormwater management plans (SWMP) are in place to address construction, drilling and operations associated with Oil & Gas development throughout the state of Colorado in accordance with Colorado Department of Public Health and Environment (CDPHE) General Permit No. COR- 038637. BMP's will be constructed around the perimeter of the site prior to, or at the beginning of construction. BMP's used will vary according to the location, and will remain in place and maintained until the pad reaches final reclamation.
General Housekeeping	Housekeeping will consist of neat and orderly storage of materials and fluids. Wastes will be temporarily stored in sealed containers and regularly collected and disposed of at offsite, suitable facilities. If spills occur prompt cleanup is required to minimize any commingling of waste materials with stormwater runoff. Routine maintenance will be limited to fueling and lubrication of equipment. Drip pans will be used during routine fueling and maintenance to contain spills or leaks. Any waste product from maintenance will be containerized and transported offsite for disposal or recycling. There will be no major equipment overhauls conducted onsite. Equipment will be transported offsite for major overhauls. Cleanup of trash and discarded materials will be conducted at the end of each work day. Cleanup will consist of patrolling the roadway, access areas, and other work areas to pickup trash, scrap debris, other discarded materials, and any contaminated soil. These materials will be disposed of properly.
Material Handling and Spill Prevention	Spill Prevention Control and Countermeasures (SPCC) plans are in place to address any possible spill associated with Oil & Gas operations throughout the state of Colorado in accordance with CFR 112.

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Inspector Name: Trujillo, Aaron

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____
 Request LGD Attendance: _____
LGD Contact Information:
 Name: _____ Phone Number: _____ Agreed to Attend: _____
Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID:	437719	Type:	WELL	API Number:	123-39649	Status:	PR	Insp. Status:	RI
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: PR

Facility ID:	437724	Type:	WELL	API Number:	123-39652	Status:	PR	Insp. Status:	RI
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: PR

Facility ID:	437727	Type:	WELL	API Number:	123-39654	Status:	PR	Insp. Status:	RI
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: PR

Facility ID:	437746	Type:	WELL	API Number:	123-39663	Status:	PR	Insp. Status:	RI
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: PR

Facility ID:	437759	Type:	WELL	API Number:	123-39672	Status:	PR	Insp. Status:	RI
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: PR

Facility ID:	437777	Type:	WELL	API Number:	123-39686	Status:	PR	Insp. Status:	RI
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: PR

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:		Lat	Long
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	
Field Parameters:			
Sample Location: _____			
Emission Control Burner (ECB): _____			
Comment: _____			
Pilot: _____ Wildlife Protection Devices (fired vessels): _____			

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-CroplandTop soil replaced _____ Recontoured Pass 80% Revegetation In1003 f. Weeds Noxious weeds? PComment: Location footprint has been reduced in size. Location has been recently seeded and crimped, seed gemination evident.

Overall Interim Reclamation	In Process
-----------------------------	------------

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682500618	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3827546