



Photo #1:
Overview of Location to East.

Photo#2:

Guy Anchors not removed

Photo#3:



Photo#4:

Gravel not removed



Photo#5:

Facilities to be identified






Photo #6:
Overview of Location to West.

April 10, 2016

Inspection Photos WPX PA # 045-06351