



Photo #1:

Conductor with Welded Cap (?), Status to be determined.

Inspection Photos NW Exploration AL # 045-06226

April 10, 2016

Photo#2:

View North over Location



Photo#3:

View South over Location



April 10, 2016

Inspection Photos NW Exploration AL # 045-06226

Photo#4:

View East over Location



Photo#5:

View West over Location



Inspection Photos NW Exploration AL # 045-06226

April 10, 2016



Photo #6:

Overview of Pit area at North side of Location looking West.

Inspection Photos NW Exploration AL # 045-06226

April 10, 2016