


## Photo#1:

View North over Location



## Photo#2:

View South over Location



### Photo#3:

View East over Location



### Photo#4:

View West over Location





## Photo#5:

Senesced Musk Thistle, establishing



## Photo#6:

Compacted Area with Debris





Photo#7:

Associated Facilities on location : Identify and remove /close those specific to servicing this P&A Location



Photo#8:





Photo#9:

Gravel and Rock not removed



Photo#10:

