

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401019999

Date Received:

04/01/2016

Spill report taken by:

ALLISON, RICK

Spill/Release Point ID:

445284

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: GREAT WESTERN OPERATING COMPANY LLC	Operator No: 10110	<b>Phone Numbers</b>
Address: 1801 BROADWAY #500		Phone: (303) 398-0302
City: DENVER	State: CO	Zip: 80202
Contact Person: Scot Donato		Mobile: (303) 549-7739
		Email: sdonato@gwogco.com

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 401015105

Initial Report Date: 03/24/2016 Date of Discovery: 03/22/2016 Spill Type: Historical Release

Spill/Release Point Location:

Location of Spill/Release: QTRQTR NESE SEC 15 TWP 6N RNG 67W MERIDIAN 6

Latitude: 40.484493 Longitude: -104.872766

Municipality (if within municipal boundaries): Windsor County: WELD

Reference Location:

Facility Type: TANK BATTERY  Facility/Location ID No 319611  
 No Existing Facility or Location ID No.  
 Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? No

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? No

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0 Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): Unknown

Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify:

Land Use:

Current Land Use: NON-CROP LAND Other(Specify): undeveloped

Weather Condition: clear

Surface Owner: FEE Other(Specify):

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State  Residence/Occupied Structure  Livestock  Public Byway  Surface Water Supply Area

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

GWOC recently relocated the Haas #1 Tank Battery. As a result of that process, GWOC identified a historical release of produced water. impacted soils were noted and excavated. Soil samples collected from the walls and base of the excavation, and from the stockpile contained concentrations of TPH which exceed Table 910-1 concentrations.

**List Agencies and Other Parties Notified:**

**OTHER NOTIFICATIONS**

Date	Agency/Party	Contact	Phone	Response
3/22/2016	COGCC	Rick Allison	-	notified by email
3/22/2016	Weld County	Troy Swain	-	notified by email
3/24/2016	Town of Windsor	Joe Plummer	-	notified by email
3/22/2016	Surface Owner	Journey Homes	-	notified by email

**SPILL/RELEASE DETAIL REPORTS**

#1 Supplemental Report Date: 04/01/2016

<b>FLUIDS</b>	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	<u>0</u>	<u>0</u>	<input type="checkbox"/>
CONDENSATE	<u>0</u>	<u>0</u>	<input type="checkbox"/>
PRODUCED WATER			<input checked="" type="checkbox"/>
DRILLING FLUID	<u>0</u>	<u>0</u>	<input type="checkbox"/>
FLOW BACK FLUID	<u>0</u>	<u>0</u>	<input type="checkbox"/>
OTHER E&P WASTE	<u>0</u>	<u>0</u>	<input type="checkbox"/>

specify: \_\_\_\_\_

Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO

*Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

**A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit**

Impacted Media (Check all that apply)  Soil  Groundwater  Surface Water  Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): 0 Width of Impact (feet): 0

Depth of Impact (feet BGS): 0 Depth of Impact (inches BGS): \_\_\_\_\_

How was extent determined?

Extent has not been fully determined yet, but will be during additional excavation and/or drilling activities. The site is currently inaccessible due to significant snowfall and mud conditions.

Soil/Geology Description:

Kim Loam, 1 to 3 percent slopes

Depth to Groundwater (feet BGS) 0 Number Water Wells within 1/2 mile radius: 7

If less than 1 mile, distance in feet to nearest

Water Well	<u>190</u>	None <input type="checkbox"/>	Surface Water	<u>200</u>	None <input type="checkbox"/>
Wetlands	<u>0</u>	None <input type="checkbox"/>	Springs	<u>0</u>	None <input type="checkbox"/>
Livestock	<u>0</u>	None <input type="checkbox"/>	Occupied Building	<u>1600</u>	None <input type="checkbox"/>

Additional Spill Details Not Provided Above:

## REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure:  Corrective Actions Completed (documentation attached)

Work proceeding under an approved Form 27

Form 27 Remediation Project No: \_\_\_\_\_

### OPERATOR COMMENTS:

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Rachel Peterson

Title: Project Manager Date: 04/01/2016 Email: petersonr@agwassenaar.com

### COA Type

### Description

COA Type	Description

## Attachment Check List

### Att Doc Num

### Name

Att Doc Num	Name
401019999	FORM 19 SUBMITTED

Total Attach: 1 Files

## General Comments

### User Group

### Comment

### Comment Date

User Group	Comment	Comment Date
Environmental	Operator is requested to verify the location of the water well identified to be 190 feet from the reported release point. If the water well is incorrectly located based on DWR historical records, then submit a revised Spill/Release Detail Report with a corrected distance to the nearest water well. If the water well is verified to be mapped correctly or is found to be located within 1/8 mile of the release, then include the water well location on site diagrams with future reports.	4/6/2016 9:44:53 AM

Total: 1 comment(s)