



Photo#1: View of Location to NE from Gate off HWY 64.

April 11, 2016

Inspection Photos: Chesapeake OP #103-07411



Photo#2:

High Animal Impact is restricting Revegetation and promoting Weed growth.

Photo#3:







Photo#4: Associated Facilities on Location

Inspection Photos: Chesapeake OP #103-07411

April 11, 2016



Photo#5:

Photo#6:

Debris and Trash on Location.



April 11, 2016

Inspection Photos: Chesapeake OP #103-07411