



Photo#1: Overview of Location to West from Access Road Entry.


April 24, 2016

Inspection Photos: WPX Federal SG Loc#334978

Photo#2:

Photo#3:

Vehicles are tracking into Interim Reclamation areas.





Photo#4:

Point where Sediment/SW enters Location BMPs @ SW Corner.



Photo#5:

SW Ditch overwhelmed with Sediment

