

Final Reclamation Inspection- Abandoned Location



Photo 1. Photo taken of PR well sign 123-12634.

Final Reclamation Inspection- Abandoned Location



Photo 2. Photo taken from east of location, facing West. It does not appear that well APIs 123-31246 and 123-31247 were constructed at this location. This is a release on an active location.