



photo 1: Facing west along the former access road. Straw mulch has been applied and crimped into the soil.



photo 2: East side of the location facing west. Straw mulch has been applied and crimped into the soil.



photo 3: South side of the location facing north. Straw mulch is providing temporary soil stabilization.



photo 4: Facing toward the surrounding previous crop.