

P&A Well Site Evaluation

Well Location

Mages 1

API#

05-103-05808

P&A Date

1/19/88

Inspection Date

4/22/16

Location Photos

4

Vegetation

Very good, large sals
grasses

Trash

None

Access Road

P&A marker is about 20'
off the west edge
of Mages 1A

Contouring Issues

None

Stormwater Issues

None

Ready for FAN

Yes

Fee



Mager 1
05-103-05808
East

Magor 1
05-103-05808
West

05-103-05808
Magor 1
West





Major 1
05-103-05808
South

CLAYTON

