



Photo#1: View of Location from Access Road Entry to East.

May 2, 2016

Inspection Photos: WPX UNOCAL API# 077-07744



Photo#2: Interim Reclamation installed at SE end of Location.

Inspection Photos: WPX UNOCAL API# 077-07744

May 2, 2016





Photo#3: View of Location to NW; P&A Marker installed

Inspection Photos: WPX UNOCAL API# 077-07744

May 2, 2016