

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/05/2016

Document Number:

673403167

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	412905	413908	Waldron, Emily	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Laird, Spence		slaird@sandridgeenergy.com	
Niven, Jason	405-441-0155	jniven@sandridgeenergy.com	

**Compliance Summary:**QtrQtr: NENE Sec: 12 Twp: 7N Range: 81W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
11/03/2015	673402616	PR	PR	SATISFACTORY			No
02/11/2015	673401786			SATISFACTORY			No
09/16/2014	673401115	DG	PR	ACTION REQUIRED			No

**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412827	WELL	AL	03/10/2015	LO	057-06494	MARR 4-12H	AL <input type="checkbox"/>
412905	WELL	PR	05/15/2015	OW	057-06498	Hebron 3-12H	PR <input checked="" type="checkbox"/>
444502	SPILL OR RELEASE	CL	01/08/2016		-	SPILL/RELEASE POINT	CL <input type="checkbox"/>

**Equipment:****Location Inventory**

Special Purpose Pits: _____	Drilling Pits: <u>1</u>	Wells: <u>1</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>2</u>	Separators: <u>2</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: <u>2</u>	LACT Unit: <u>1</u>	Pump Jacks: <u>1</u>
Electric Generators: <u>1</u>	Gas Pipeline: <u>1</u>	Oil Pipeline: <u>1</u>	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: <u>1</u>	Oil Tanks: <u>5</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: <u>1</u>	Fuel Tanks: _____

**Location**

Inspector Name: Waldron, Emily

<b>Lease Road:</b>				
Type	Satisfactory/Action Required	comment	Corrective Action	Date

<b>Signs/Marker:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: \_\_\_\_\_

Comment: 405-429-5974

Corrective Action: \_\_\_\_\_

<b>Good Housekeeping:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Fencing/:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

<b>Equipment:</b>				
Type: Pump Jack	# 1	Satisfactory/Action Required:	SATISFACTORY	
Comment				
Corrective Action				Date: <span style="color: red;"> </span>
Type: Deadman # & Marked	# 4	Satisfactory/Action Required:	SATISFACTORY	
Comment				
Corrective Action				Date: <span style="color: red;"> </span>

<b>Venting:</b>	
Yes/No	NO
Comment	

<b>Flaring:</b>			
Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

<b>Predrill</b>			
Location ID: <u>412905</u>			
Lease Road Adeq.: _____		Pads: _____	Soil Stockpile: _____
S/AR: _____			

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

Group	User	Comment	Date
OGLA	kubeczkod	Location is in a sensitive area because shallow groundwater; therefore either a lined drilling pit or closed loop system (which EOG has indicated on the Form 2A) must be implemented.	01/01/2011
OGLA	kubeczkod	Operator must ensure 110 percent secondary containment for any volume of fluids contained at well site during drilling and completion operations; including, but not limited to, construction of a berm or diversion dike, diversion/collection trenches within and/or outside of berms/dikes, site grading, or other comparable measures sufficiently protective of nearby surface water.	01/01/2011
OGLA	kubeczkod	Operator must implement best management practices to contain any unintentional release of fluids, including any fluids conveyed via temporary surface pipelines.	01/01/2011
OGLA	kubeczkod	Reserve pit must be lined or a closed loop system (which EOG has indicated on the Form 2A) must be implemented during drilling.	01/01/2011
OGLA	kubeczkod	The moisture content of any drill cuttings in a cuttings pit, trench, or pile shall be as low as practicable to prevent accumulation of liquids greater than de minimis amounts. At the time of closure, the drill cuttings must also meet the applicable standards of table 910-1.	01/01/2011

**S/AR:** SATISFACTORY**Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_**Date:** \_\_\_\_\_**Wildlife BMPs:****S/AR:** \_\_\_\_\_**Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_**Date:** \_\_\_\_\_**Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Inspector Name: Waldron, Emily

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

### Facility

Facility ID: 412905 Type: WELL API Number: 057-06498 Status: PR Insp. Status: PR

### Producing Well

Comment: Pumping.

### Environmental

#### Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:  
Comment:  
Corrective Action: Date:  
Reportable: GPS: Lat Long  
Proximity to Surface Water: Depth to Ground Water:

#### Water Well:

DWR Receipt Num: Owner Name: GPS : Lat Long

#### Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

### Reclamation - Storm Water - Pit

#### Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use: RANGELAND

Comment:

1003a. Waste and Debris removed?

CM

CA CA Date

Unused or unneeded equipment onsite?

CM

CA CA Date

Pit, cellars, rat holes and other bores closed?

CM

CA CA Date

Guy line anchors marked?

CM

CA \_\_\_\_\_

CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_

Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_

Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_

Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: SATISFACTOR

Corrective Date: \_\_\_\_\_

Y

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673403167	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3851118">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3851118</a>