

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/16/2016

Document Number:

678800061

Overall Inspection:

ACTION REQUIRED**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	286723	336027	LEONARD, MIKE	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1050 17TH STREET #1700City: DENVER State: CO Zip: 80265

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
		dknudson@ursaresources.com	

Compliance Summary:QtrQtr: Lot 4 Sec: 7 Twp: 6S Range: 92W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
07/29/2015	666801220	PR	PR	SATISFACTORY			No
11/14/2014	666800289	PR	PR	SATISFACTORY			No
10/04/2013	670200928	PR	PR	SATISFACTORY			No
06/28/2010	200265068	SR	PR	SATISFACTORY			No

Inspector Comment:

This Inspection document is for testing of the Field inspection Resolution Form and process. No actual corrective actions were found on this location as documented by this form.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286722	WELL	XX	09/04/2011	LO	045-12745	COLOROSO A2	XX
286723	WELL	PR	11/01/2007	GW	045-12744	COLOROSO A3	PR
286758	WELL	PR	10/04/2012	GW	045-12746	COLOROSO A4	PR
288253	WELL	XX	09/04/2011	LO	045-13175	COLOROSO A8	XX
288254	WELL	PR	11/01/2007	GW	045-13174	COLOROSO A7	PR
288255	WELL	XX	09/04/2011	LO	045-13173	COLOROSO A6	XX
288256	WELL	XX	09/04/2011	LO	045-13172	COLOROSO A5	XX
296467	WELL	XX	09/04/2011	LO	045-16044	COLOROSO A10	XX

Inspector Name: LEONARD, MIKE

296468	WELL	XX	09/04/2011	LO	045-16045	COLOROSO A9	XX	<input type="checkbox"/>
297193	WELL	XX	09/04/2011	LO	045-16336	COLOROSO A1	XX	<input type="checkbox"/>
297194	WELL	PR	07/16/2008	GW	045-16337	COLOROSO A11	PR	<input type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	ACTION REQUIRED		This Inspection document is for testing of the Field inspection Resolution Form and process. No actual corrective actions were found on this location as documented by this form.	05/26/2016

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Emergency Contact Number (S/AR): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
OTHER	ACTION REQUIRED		This Inspection document is for testing of the Field inspection Resolution Form and process. No actual corrective actions were found on this location as documented by this form.	05/26/2016

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
OTHER	ACTION REQUIRED		This Inspection document is for testing of the Field inspection Resolution Form and process. No actual corrective actions were found on this location as documented by this form. Changing text testing factual review	05/26/2016

Equipment:				
Type:	#	Satisfactory/Action Required:		
Comment				
Corrective Action				Date:

Venting:	
Yes/No	
Comment	

Flaring:			
Type		Satisfactory/Action Required	
Comment:			
Corrective Action:			Correct Action Date:

Predrill

Location ID: 286723

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 0 Type: _____ API Number: - Status: _____ Insp. Status: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Inspector Name: LEONARD, MIKE

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____

Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____

Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____

CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____

CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____

CA Date _____

Guy line anchors marked? _____

CM _____

CA _____

CA Date _____

1003b. Area no longer in use? _____

Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____

Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Inspector Name: LEONARD, MIKE

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other						

S/A/V: **ACTION REQUIRED** Corrective Date: **05/26/2016**

Comment: _____

CA: **This Inspection document is for testing of the Field inspection Resolution Form and process. No actual corrective actions were found on this location as documented by this form.**

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
This Inspection document is for testing of the Field inspection Resolution Form and process. No actual corrective actions were found on this location as documented by this form.	leonardm	05/16/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
678800061	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3861849