

Fuqua 19-02-10-1H

Inspection# 673403187

Former operator on battery sign located at entrance to location.



1 of 3 tanks labeled as both produced water and crude oil. Previous operator contact information on all tanks.



1 of 2 unlabeled tanks with stained soil around base.



Equipment stored on location.

