

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/31/2016

Document Number:

675202878

Overall Inspection:

SATISFACTORY w/ CMT
or AR**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	334543	334543	CONKLIN, CURTIS	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Bankert, Wayne	(970) 683-5419	wbankert@laramie-energy.com	Senior Regulatory & Environmental Coordinator
Kellerby, Shaun		shaun.kellerby@state.co.us	NW Supervisor

Compliance Summary:QtrQtr: NESE Sec: 10 Twp: 10S Range: 94W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
01/25/2016	675202441			SATISFACTORY			No
07/13/2015	675201772			SATISFACTORY			No
02/10/2015	675201187			SATISFACTORY			No
08/13/2014	675200400			SATISFACTORY			No

Inspector Comment:

Inspection in response to Flash Flood incident. County doing repairs on Salt Creek Road at time of inspection, therefore limiting access. The majority of the location is covered in sediment. Wells shut in on 5/27/16 in response to incident. No visible signs of spills or leaks.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
243	WELL	PR	10/14/2008	GW	077-09482	HAWKINS RANCH 10-8C	SI	<input checked="" type="checkbox"/>
370	WELL	PR	02/01/2015	GW	077-09483	HAWKINS RANCH 10-9	SI	<input checked="" type="checkbox"/>
371	WELL	PR	10/19/2008	GW	077-09484	HAWKINS RANCH 10-9A	SI	<input checked="" type="checkbox"/>
372	WELL	PR	11/17/2008	GW	077-09485	HAWKINS RANCH 10-8B	SI	<input checked="" type="checkbox"/>
386	WELL	PR	09/28/2008	GW	077-09486	HAWKINS RANCH 10-7C	SI	<input checked="" type="checkbox"/>
387	WELL	PR	10/12/2008	GW	077-09487	HAWKINS RANCH 10-7B	SI	<input checked="" type="checkbox"/>
388	WELL	PR	12/09/2008	GW	077-09488	HAWKINS RANCH 10-6	SI	<input checked="" type="checkbox"/>

Inspector Name: CONKLIN, CURTIS

389	WELL	PR	01/06/2009	GW	077-09489	HAWKINS RANCH 10-7A	SI	<input checked="" type="checkbox"/>
390	WELL	PR	07/19/2010	GW	077-09490	HAWKINS RANCH 10-7	SI	<input checked="" type="checkbox"/>
391	WELL	PR	11/02/2008	GW	077-09491	HAWKINS RANCH 10-6B	SI	<input checked="" type="checkbox"/>
392	WELL	PR	10/19/2008	GW	077-09492	HAWKINS RANCH 10-6A	SI	<input checked="" type="checkbox"/>
393	WELL	PR	12/01/2014	GW	077-09493	HAWKINS RANCH 10-10A	SI	<input checked="" type="checkbox"/>
394	WELL	PR	12/09/2008	GW	077-09494	HAWKINS RANCH 10-10	SI	<input checked="" type="checkbox"/>
395	WELL	PR	08/01/2012	GW	077-09495	HAWKINS RANCH 10-8	SI	<input checked="" type="checkbox"/>
294989	WELL	PR	09/22/2008	GW	077-09538	HAWKINS RANCH 10-8A	SI	<input checked="" type="checkbox"/>
294993	WELL	PR	11/28/2008	GW	077-09537	HAWKINS RANCH 10-6C	SI	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	SATISFACTORY			
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:				
Type:	#	Satisfactory/Action Required:		
Comment				
Corrective Action				Date:

Facilities:				
<input type="checkbox"/> New Tank		Tank ID: _____		
Contents	#	Capacity	Type	SE GPS
CONDENSATE	6	400 BBLS	STEEL AST	,
S/AR	SATISFACTORY	Comment:	AIRS ID 077-0477-022	
Corrective Action:				Corrective Date:

Paint	
Condition	Adequate
Other (Content)	_____
Other (Capacity)	_____
Other (Type)	_____

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Corrective Action				Corrective Date
Comment	Sediment in and around containment			

Venting:	
Yes/No	NO
Comment	

Flaring:			
Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 334543

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 243 Type: WELL API Number: 077-09482 Status: PR Insp. Status: SI

Facility ID: 370 Type: WELL API Number: 077-09483 Status: PR Insp. Status: SI

Facility ID: 371 Type: WELL API Number: 077-09484 Status: PR Insp. Status: SI

Facility ID: 372 Type: WELL API Number: 077-09485 Status: PR Insp. Status: SI

Facility ID: 386 Type: WELL API Number: 077-09486 Status: PR Insp. Status: SI

Facility ID: 387 Type: WELL API Number: 077-09487 Status: PR Insp. Status: SI

Facility ID: 388 Type: WELL API Number: 077-09488 Status: PR Insp. Status: SI

Facility ID: 389	Type: WELL	API Number: 077-09489	Status: PR	Insp. Status: SI
Facility ID: 390	Type: WELL	API Number: 077-09490	Status: PR	Insp. Status: SI
Facility ID: 391	Type: WELL	API Number: 077-09491	Status: PR	Insp. Status: SI
Facility ID: 392	Type: WELL	API Number: 077-09492	Status: PR	Insp. Status: SI
Facility ID: 393	Type: WELL	API Number: 077-09493	Status: PR	Insp. Status: SI
Facility ID: 394	Type: WELL	API Number: 077-09494	Status: PR	Insp. Status: SI
Facility ID: 395	Type: WELL	API Number: 077-09495	Status: PR	Insp. Status: SI
Facility ID: 294989	Type: WELL	API Number: 077-09538	Status: PR	Insp. Status: SI
Facility ID: 294993	Type: WELL	API Number: 077-09537	Status: PR	Insp. Status: SI

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____

CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____

CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____

CA Date _____

Guy line anchors marked? _____

CM _____

CA _____

CA Date _____

1003b. Area no longer in use? _____

Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____

Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads _____

Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Inspector Name: CONKLIN, CURTIS

Overall Final Reclamation _____	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>
---------------------------------	--	--

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
COGCC staff will do follow up inspection once pad clean up has been started.	conklinc	05/31/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675202878	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3868175
675202879	Location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3868173