

Final Reclamation Inspection



Photo 1. Google Earth aerial imagery taken 2/29/2008 of the total disturbance.

Final Reclamation Inspection



Photo 2. Photo taken from center of location, facing West. Need to reclaim well location per Rule 1004. Location has 3 List B Colorado Noxious weeds.

Final Reclamation Inspection



Photo 3. Photo taken from center of location, facing North. Need to reclaim well location per Rule 1004. Location has 3 List B Colorado Noxious weeds.

Final Reclamation Inspection



Photo 4. Photo taken from center of location, facing East. Need to reclaim well location per Rule 1004. Location has 3 List B Colorado Noxious weeds.

Final Reclamation Inspection



Photo 5. Photo taken from center of location, facing South. Need to reclaim well location per Rule 1004. Location has 3 List B Colorado Noxious weeds.

Final Reclamation Inspection



Photo 6. Photo taken from eastern location, facing South. Need to reclaim well location per Rule 1004. It appears the location was never cross-ripped to alleviate compaction because little to no vegetative growth is establishing.

Final Reclamation Inspection



Photo 7. Photo taken of a List B Colorado Noxious weed species, Scotch thistle (*Onopordum* sp.).

Final Reclamation Inspection



Photo 8. Photo taken of a List B Colorado Noxious weed species, Hoary cress (*Cardaria draba*)

Final Reclamation Inspection



Photo 9. Photo taken of a List B Colorado Noxious weed species, Musk thistle (*Carduus nutans*).