



Photo#1: Vegetation is progressing

June 2, 2016

Inspection Photos: OXY PA Cascade Creek 045-06870



Photo#2: Sparse revegetation in spots

Inspection Photos: OXY PA Cascade Creek 045-06870

June 2, 2016



Photo#3: Bare spots with no emerging Vegetation.

Inspection Photos: OXY PA Cascade Creek 045-06870

June 2, 2016



Photo#4: A few Houndstongue Rosettes were noted.

Inspection Photos: OXY PA Cascade Creek 045-06870

June 2, 2016



Photo#5: Orchard Grass appears to be the Predominant emergent Species.

Inspection Photos: OXY PA Cascade Creek 045-06870

June 2, 2016