



Photo#1: There is no evidence of these Two P&A Wells on this Active Location.

June 2, 2016

Inspection Photos: OXY PA- DA Cascade Creek



Photo#2: There is no evidence of the Two P&A Wells on this Active Location.

Inspection Photos: OXY PA- DA Cascade Creek

June 2, 2016