



Photo#1: Much of Location is used as Land Farming Site (Facility ID# **#443325**).

June 3, 2016

Inspection Photos: Linn Operating Loc#335658



Photo#2: Straw bales need to be maintained.

Inspection Photos: Linn Operating Loc#335658

June 3, 2016



Photo#3: Rock Socks need maintenance

Inspection Photos: Linn Operating Loc#335658

June 3, 2016