

Final Reclamation Inspection



Photo 1. Photo taken from west of location, facing East. Location 336656 has 4 active wells.

Final Reclamation Inspection



Photo 2. Photo taken of PR well sign for API #123-17594.

Final Reclamation Inspection



Photo 3. Photo taken of PR well sign for API #123-17595.

Final Reclamation Inspection



Photo 4. Photo taken of PR well sign for API #123-17538.

Final Reclamation Inspection



Photo 5. Photo taken of PR well sign for API #123-23404.