

Final Reclamation Inspection



Photo 1. Photo taken from western location, facing East. Location ID 418834 is an active, multi-well location. Therefore, this is a well release for API #123-32023 on an active location which was DA in 2013.