

**FORM INSP**  
Rev 05/11

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
06/09/2016  
Document Number:  
674602547  
Overall Inspection:  
SATISFACTORY

**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>214166</u>	<u>333518</u>	<u>Maclaren, Joe</u>	<input type="checkbox"/>	

**Operator Information:**

OGCC Operator Number:	<u>96705</u>
Name of Operator:	<u>WPX ENERGY PRODUCTION LLC</u>
Address:	<u>P O BOX 3102 MS-25-2</u>
City:	<u>TULSA</u> State: <u>OK</u> Zip: <u>74101</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, WPX	970-263-2716	COGCCInspectionReportsSanJuan@wpxenergy.com	WPX Inspection Mailbox
Hazard, Ellice		ellice.hazard@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Compliance Summary:**

QtrQtr: <u>SWNE</u>		Sec: <u>7</u>		Twp: <u>33N</u>		Range: <u>9W</u>	
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
02/17/2016	685300027	PR	PR	SATISFACTORY			No
03/14/2012	661700176	PR	PR	SATISFACTORY	P		No
10/26/2010	200281168	PR	PR	SATISFACTORY			No
02/29/2008	200127461	PR	PR	SATISFACTORY			No
07/25/2007	200120665	PR	PR	SATISFACTORY			No
03/07/2006	200088522	PR	PR	SATISFACTORY		Pass	No
10/14/2004	200065564	PR	PR	SATISFACTORY		Pass	No
04/02/2003	200037989	PR	PR	SATISFACTORY		Pass	No
09/13/2001	200021611	PR	PR	SATISFACTORY		Pass	No
04/17/2000	200006785	BH	PR	SATISFACTORY		Pass	No
09/24/1999	500146890	CO	PR			Pass	No
09/10/1999	200010314	ES	PR	SATISFACTORY		Fail	Yes
09/10/1999	500146889	CO	PR			Fail	Yes
12/30/1997	500146888	PR	PR			Pass	No
04/23/1996	500146887	BH	PR			Pass	No
02/15/1996	500146885	PR	PR				No
05/24/1995	500146884	BH	PR				No
10/20/1994	500146886	PR	PR			Fail	Yes

**Inspector Comment:**

On June 6th, 2016 COGCC Integrity Inspector Joe MacLaren met with WPX Energy's Production Foreman Darren Rowley on location and conducted an engineering integrity field inspection. Details of the WPX integrity program for the flowlines associated with this well site were reviewed. More information is outlined in the equipment/ flowline section of this report. Photo's and 2015 pressure testing documents have been uploaded and can be accessed via link(s) at the end of this report. This is an engineering integrity field inspection (only).

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
214166	WELL	PR	11/11/1955	GW	067-05486	BONDAD 33-9 6	EG	<input checked="" type="checkbox"/>
215306	WELL	PR	12/17/1987	GW	067-06911	LYLE SHORT A 1	PR	<input type="checkbox"/>

**Equipment:**

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date

**Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Emergency Contact Number (S/AR): \_\_\_\_\_

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Good Housekeeping:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Spills:**

Type	Area	Volume	Corrective action	CA Date

Multiple Spills and Releases?

**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Equipment:**

Type: Flow Line	#	Satisfactory/Action Required:
		SATISFACTORY

Comment	<p>The WPX flowlines at this well site were identified; Integrity management specifics for the WPX flowlines were reviewed while on location; Integrity topics discussed included (but were not limited to) Cathodic Protection, Corrosion Chemical Treatments, Flowline Materials/ Appurtenances, AVO Inspections and Annual Flowline Pressure Testing; The 2015 Pressure testing records (conducted on 10/12/15) for the flowlines at this well site were requested and reviewed; No flowline integrity issues were identified at the time of this field inspection. Note: Many of the gas lines associated with this location are operated by Williams Field Services (based on existing locations of custody transfers).</p>		
Corrective Action		Date:	

<b>Venting:</b>	
Yes/No	
Comment	

<b>Flaring:</b>			
Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

**Predrill**

Location ID: 214166

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

S/AR: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

Comment: \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 214166 Type: WELL API Number: 067-05486 Status: PR Insp. Status: EG

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS: \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Inspector Name: Maclaren, Joe

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674602563	2015 Flowline Pressure Testing Chart	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3875357">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3875357</a>
674602564	Well Sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3875358">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3875358</a>
674602565	Wellhead and Chemical Injector	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3875359">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3875359</a>
674602566	Dehydrator, PW Tank and Compressor (Williams)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3875360">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3875360</a>