

Craig 1-7

Inspection# 673403260

Stained soil from pump jack exhaust.



Stained soil.



Close up of stained soil pile. Hard hat for scale.



Vegetation growing on and in berm.



Stained soil at tank base.
Hard hat for scale.

