

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/22/2016

Document Number:

668004537

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	217644	333519	DURAN, JOHN	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10084Name of Operator: PIONEER NATURAL RESOURCES USA INCAddress: 5205 N O'CONNOR BLVD STE 200City: IRVING State: TX Zip: 75039

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	All Inspections

Compliance Summary:QtrQtr: SWSE Sec: 4 Twp: 33S Range: 65W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
12/01/2014	668002887	PR	PR	SATISFACTORY	P		No
05/07/2009	200209908	PR	PR	SATISFACTORY			No
01/26/2006	200083579	PR	PR	SATISFACTORY		Pass	No
01/10/2004	200048763	PR	PR	SATISFACTORY		Pass	No
09/04/1998	500151948	SR	SI			Pass	No
07/08/1997	500151947	PR	PR			Pass	No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
112904	PIT	AC	09/23/1999		-	SAWTOOTH 34-4	AC	<input type="checkbox"/>
113378	PIT	AC	09/23/1999		-	SAWTOOTH 34-4	AC	<input type="checkbox"/>
217644	WELL	PR	11/09/2003	GW	071-06423	SAWTOOTH 34-4	PR	<input checked="" type="checkbox"/>
217927	WELL	IJ	10/12/2007	DSPW	071-06706	SAWTOOTH 34-4 WD	IJ	<input type="checkbox"/>
282351	PIT	AC	12/30/2005		-	SAWTOOTH 34-4 WD	AC	<input type="checkbox"/>

Equipment:**Location Inventory**

Inspector Name: DURAN, JOHN

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:

Type: Vertical Separator	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date: _____
Type: Gas Meter Run	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date: _____
Type: Deadman # & Marked	# 4	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date: _____
Type: Progressive Cavity	# 1	Satisfactory/Action Required:	SATISFACTORY

Inspector Name: DURAN, JOHN

Comment	
Corrective Action	Date:

Venting:

Yes/No	
Comment	

Flaring:

Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 217644

Lease Road Adeq.: Pads: Soil Stockpile:

S/AR:

Corrective Action: Date: CDP Num.:

Form 2A COAs:

S/AR: Comment:

CA: Date:

Wildlife BMPs:

S/AR: Comment:

CA: Date:

Comment:

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: Address:

Phone Number: Cell Phone:

Operator Rep. Contact Information:

Landman Name: Phone Number:

Date Onsite Request Received: Date of Rule 306 Consultation:

Request LGD Attendance:

LGD Contact Information:

Name: Phone Number: Agreed to Attend:

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 217644 Type: WELL API Number: 071-06423 Status: PR Insp. Status: PR

Producing WellComment: **PR****Environmental****Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Inspector Name: DURAN, JOHN

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

S/A/V: SATISFACTOR Corrective Date: _____

Y

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
668004537	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3886567

