

Final Reclamation Inspection



Photo 1. Photo taken from center of the location, facing Northwest. Gravel was not removed per Rule 1004, which is negatively affecting plant growth.

Final Reclamation Inspection



Photo 2. Photo taken from center of the location, facing Southwest. Gravel was not removed per Rule 1004, which is negatively affecting plant growth.

Final Reclamation Inspection



Photo 3. Photo taken from center of the location, facing North. Gravel was not removed per Rule 1004.

Final Reclamation Inspection



Photo 4. Photo taken from center of the location, facing South. Gravel was not removed per Rule 1004.