

Final Reclamation Inspection



Photo 1. Aerial imagery from 2015 using COGCC GISOnline. Access road still remains after a corrective action inspection from 2013 was issued.

Final Reclamation Inspection



Photo 2. Photo taken from center of location, facing West. Location is IN PROCESS. List C Colorado Noxious weeds (Cheatgrass and Field bindweed) are competing with desirable plant species at this current time.

Final Reclamation Inspection



Photo 3. Photo taken from center of location, facing North. Location is IN PROCESS. List C Colorado Noxious weeds (Cheatgrass and Field bindweed) are competing with desirable plant species at this current time.

Final Reclamation Inspection



Photo 4. Photo taken from center of location, facing East. Location is IN PROCESS. List C Colorado Noxious weeds (Cheatgrass and Field bindweed) are competing with desirable plant species at this current time.

Final Reclamation Inspection



Photo 5. Photo taken from center of location, facing South. Location is IN PROCESS. List C Colorado Noxious weeds (Cheatgrass and Field bindweed) are competing with desirable plant species at this current time.

Final Reclamation Inspection



Photo 6. Reference photo taken from north of location, facing North. Although cheatgrass is present in the reference area its dominance is being outcompeted by other desirable plant species.