

## Final Reclamation Inspection



**Photo 1.** Photo taken from center of location, facing West. No evidence of disturbance. Uniform vegetative growth throughout location.



## Final Reclamation Inspection



**Photo 2.** Photo taken from center of location, facing North. No evidence of disturbance. Uniform vegetative growth throughout location.



## Final Reclamation Inspection



**Photo 3.** Photo taken from center of location, facing East. No evidence of disturbance. Uniform vegetative growth throughout location.



## Final Reclamation Inspection



**Photo 4.** Photo taken from center of location, facing South. No evidence of disturbance. Uniform vegetative growth throughout location.



## Final Reclamation Inspection



**Photo 5.** Reference photo taken east of location, facing South. Location appears to be reflective of the reference area.