



CHEVRON IO1PAD | Facility ID 335693


DOCUMENT NO. 674702875—INSPECTION DATE 6/23/2016



CHEVRON I01PAD | Facility ID 335693

Document No. 674702875—Inspection date 6/23/2016

Photo 2 of 2—remove water from cellar and replace conductor lid



CHEVRON I01PAD | Facility ID 335693

Document No. 674702875—Inspection date 6/23/2016

Photo 1 of 2—remove trash from cellar