

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
07/09/2016
Document Number:
680300822
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>220968</u>	<u>312283</u>	<u>SCHURE, KYM</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>7810</u>
Name of Operator:	<u>BERENERGY CORP</u>
Address:	<u>1888 SHERMAN ST - SUITE 600</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80203</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Hall, Dan		david@energyop.com	P&A Complete
Burn, Diana		diana.burn@state.co.us	
Quint, Craig		craig.quint@state.co.us	

Compliance Summary:

QtrQtr: NESW Sec: 30 Twp: 6N Range: 54W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
07/05/2016	680300799	PR	PA	SATISFACTORY			No
05/02/2014	667200020	PR	PR	ACTION REQUIRED			No
10/11/2013	664001342	PR	PR	ALLEGED VIOLATION			Yes
08/09/2012	663300394	PR	PR	ACTION REQUIRED	I		No
02/25/2010	200233107	PR	PR	ACTION REQUIRED			Yes
04/01/2003	200037293	PR	PR	SATISFACTORY		Pass	No
01/04/1996	500153810	PR	PR			Pass	No
12/14/1995	500153809	PR	PR			Pass	No

Inspector Comment:

P&A Completion. SATISFACTORY Note to Operator: Please contact COGCC Environmental Group regarding location remediation directives and contact COGCC Reclamation Group regarding site reclamation. Remove all surface equipment. Remediate all underground lines per COGCC rules and regulations.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
220968	WELL	PR	07/14/2005	OW	075-09094	MERINO 1	PA <input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date

Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:

Type: Other	# 0	Satisfactory/Action Required: SATISFACTORY
Comment	No change in surface equipment remaining on-site. Remove all surface equipment, purge lines, cut/cap for FI prior to burial of underground lines.	
Corrective Action		Date: _____

Venting:

Yes/No	
Comment	

Flaring:

Type	Satisfactory/Action Required
Comment:	
Corrective Action:	Correct Action Date: _____

Predrill

Location ID: 220968

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 220968 Type: WELL API Number: 075-09094 Status: PR Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Yetter Well Service

Contractor Phone: 970-522-2885

Surface Casing

Cement Volume (sx): 40 +62

Circulate to Surface: YES

Cement Fall Back: NO

Top Job, 1" Volume: YES

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): 2

Good Return During Job: YES

Plugging Operations

Depth Plugs(feet range): 4964' 605' 175'

Cement Volume (sx): 2 + 40 + 62

Good Return During Job: YES

Cement Type: 15 ppg 1.15 y

Comment: P&A Completion. Day 5. Tag cement @ 300'. Perf. (4) holes @ 175'. (62) bbls., 15.0 ppg. surface plug. Good returns, plugs complete. Cut off wellhead, welded plate w/info. approx. 4-1/2' below surface elev. Backfilled excavation @ wellhead.
P&A SATISFACTORY

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Other	Pass			

S/A/V: SATISFACTOR
Y

Corrective Date: _____

Comment: Use BMP's for stormwater erosion control and management. Continue location/lease road maintenance.

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680300823	Welded cover plate	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3898620