

Final Reclamation Inspection



Photo 1. Photo taken from north of location, facing Southeast. Final Land Use has changed from cropland to an active gravel mining area. PA location is located in a water pit.

Final Reclamation Inspection



Photo 2. Photo taken from north of location, facing South. Final Land Use has changed from cropland to an active gravel mining area. PA location is located in a water pit.

Final Reclamation Inspection



Photo 3. Photo taken from north of location, facing Southwest. Final Land Use has changed from cropland to an active gravel mining area. PA location is located in a water pit.