

Final Reclamation Inspection



Photo 1. Photo taken from south of location, facing West. Final Land Use has changed from cropland to an active gravel mining area. PA location is located in a spill over water pit.

Final Reclamation Inspection



Photo 2. Photo taken from south of location, facing North. Final Land Use has changed from cropland to an active gravel mining area. PA location is located in a spill over water pit.