

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/14/2016

Document Number:

681901166

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 240685 | 318134 | HELGELAND, GARY | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 46290Name of Operator: K P KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|-------------------|--------------|---------------|----------------|
| LARA-MESA, SUSANA | 303-825-4822 | cogcc@kpk.com | VP OF ENGINEER |

Compliance Summary:QtrQtr: NESE Sec: 13 Twp: 1N Range: 68W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 09/04/2014 | 668302331 | PR | SI | ACTION REQUIRED | I | | No |
| 06/08/2007 | 200123991 | PR | PR | ACTION REQUIRED | | | Yes |
| 06/12/1997 | 500162831 | PR | PR | | | Pass | No |
| 11/14/1995 | 500162830 | PR | PR | | | Pass | No |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|--|
| 118671 | PIT | | 09/23/1999 | | - | UPRR 43 PAN AM "I" | <input type="checkbox"/> |
| 240685 | WELL | PR | 06/20/1995 | GW | 123-08473 | UPRR 43 PAN AM I 3 | PR <input checked="" type="checkbox"/> |

Equipment:**Location Inventory**

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Inspector Name: HELGELAND, GARY

| | | | | |
|--------------------|------------------------------|---------|-------------------|------|
| Lease Road: | | | | |
| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
| | | | | |

| | | | | |
|----------------------|------------------------------|---------|-------------------|---------|
| Signs/Marker: | | | | |
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| WELLHEAD | SATISFACTORY | | | |

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

| | | | | |
|---------------------------|------------------------------|---------|-------------------|---------|
| Good Housekeeping: | | | | |
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| | | | | |

| | | | | |
|----------------|------|--------|-------------------|---------|
| Spills: | | | | |
| Type | Area | Volume | Corrective action | CA Date |
| | | | | |

☐ Multiple Spills and Releases?

| | | | | |
|------------------|------------------------------|------------|-------------------|---------|
| Fencing/: | | | | |
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| WELLHEAD | SATISFACTORY | Angle iron | | |

| | | | | |
|-------------------|-----|-------------------------------|--------------|-------|
| Equipment: | | | | |
| Type: Pump Jack | # 1 | Satisfactory/Action Required: | SATISFACTORY | |
| Comment | | | | |
| Corrective Action | | | | Date: |

| | | | | |
|---|---|----------|----------------|------------------|
| Facilities: <input type="checkbox"/> New Tank Tank ID: _____ | | | | |
| Contents | # | Capacity | Type | SE GPS |
| | | | | |
| S/AR | | Comment: | REMOTE BATTERY | |
| Corrective Action: | | | | Corrective Date: |

Paint

| | |
|-----------|--|
| Condition | |
|-----------|--|

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| | | | | |
|------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |

| | | | |
|-------------------|--|-----------------|--|
| Corrective Action | | Corrective Date | |
| Comment | | | |

Venting:

| | |
|---------|----|
| Yes/No | NO |
| Comment | |

Flaring:

| | | | |
|--------------------|------------------------------|----------------------|--|
| Type | Satisfactory/Action Required | | |
| Comment: | | | |
| Corrective Action: | | Correct Action Date: | |

Predrill

Location ID: 240685

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment:**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 240685 Type: WELL API Number: 123-08473 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Bradenhead is plumed to surface.

CA:

CA Date:

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? Pass

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced Pass Recontoured Pass Perennial forage re-established In

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Gravel | Pass | | | |

S/A/V: SATISFACTOR _____ Corrective Date: _____
 Y _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Inspector Name: HELGELAND, GARY

| Document Num | Description | URL |
|--------------|---------------------|---|
| 681901166 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3904382 |