

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/14/2016

Document Number:

674702945

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	335237	335237	LONGWORTH, MIKE	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-263-2716	COGCCInspectionReports@terraep.com	TEP Inspection Mail Box

**Compliance Summary:**QtrQtr: NWSE Sec: 33 Twp: 6S Range: 96W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
01/04/2016	674702234			SATISFACTORY			No
11/03/2014	674700533			SATISFACTORY			No

**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
210861	WELL	PR	10/01/1995	GW	045-06619	UNION GV 5-33	PR	<input checked="" type="checkbox"/>
260719	WELL	PR	07/20/2001	GW	045-07904	UNOCAL GM 533-33	PR	<input checked="" type="checkbox"/>

**Equipment:**Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

<b>Lease Road:</b>				
Type	Satisfactory/Action Required	comment	Corrective Action	Date

<b>Signs/Marker:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
BATTERY	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: \_\_\_\_\_

Comment: 970-285-9377

Corrective Action: \_\_\_\_\_

<b>Good Housekeeping:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Fencing/:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
TANK BATTERY	SATISFACTORY			
SEPARATOR	SATISFACTORY			

<b>Equipment:</b>				
Type: Bird Protectors	# 3	Satisfactory/Action Required: SATISFACTORY		
Comment				
Corrective Action		Date: _____		
Type: Plunger Lift	# 2	Satisfactory/Action Required: SATISFACTORY		
Comment				
Corrective Action		Date: _____		
Type: Dehydrator	# 1	Satisfactory/Action Required: SATISFACTORY		
Comment				
Corrective Action		Date: _____		
Type: Horizontal Heated Separator	# 2	Satisfactory/Action Required: SATISFACTORY		
Comment				
Corrective Action		Date: _____		

**Facilities:** ☐ New Tank Tank ID: \_\_\_\_\_

Inspector Name: LONGWORTH, MIKE

Contents		#	Capacity	Type	SE GPS		
PRODUCED WATER		1	<100 BBLS	STEEL AST	,		
S/AR	SATISFACTORY		Comment:				
Corrective Action:						Corrective Date:	
<b>Paint</b>							
Condition		Adequate					
Other (Content) _____							
Other (Capacity) _____							
Other (Type) _____							
<b>Berms</b>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate			
Corrective Action						Corrective Date	
Comment							
<b>Venting:</b>							
Yes/No	YES						
Comment	Bradens are open to vent.						
<b>Flaring:</b>							
Type		Satisfactory/Action Required					
Comment:							
Corrective Action:						Correct Action Date:	

**Predrill**

Location ID: 335237

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

**S/AR:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 210861 Type: WELL API Number: 045-06619 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID: 260719 Type: WELL API Number: 045-07904 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Inspector Name: LONGWORTH, MIKE

Corrective Action: _____		Date: _____	
Reportable: _____	GPS: Lat _____	Long _____	
Proximity to Surface Water: _____		Depth to Ground Water: _____	
<b>Water Well:</b>			
DWR Receipt Num: _____		Owner Name: _____	GPS : _____
<b>Field Parameters:</b>			
Sample Location: _____			
Emission Control Burner (ECB): _____			
Comment: _____			
Pilot: _____		Wildlife Protection Devices (fired vessels): _____	
<b>Reclamation - Storm Water - Pit</b>			
<b>Interim Reclamation:</b>			
Date Interim Reclamation Started: _____		Date Interim Reclamation Completed: _____	
Land Use: _____			
Comment: _____			
1003a. Waste and Debris removed? <u>Pass</u>			
CM _____			
CA _____		CA Date _____	
Unused or unneeded equipment onsite? <u>Pass</u>			
CM _____			
CA _____		CA Date _____	
Pit, cellars, rat holes and other bores closed? <u>Pass</u>			
CM _____			
CA _____		CA Date _____	
Guy line anchors marked? <u>Pass</u>			
CM _____			
CA _____		CA Date _____	
1003b. Area no longer in use? _____		Production areas stabilized ? _____	
1003c. Compacted areas have been cross ripped? _____			
1003d. Drilling pit closed? _____		Subsidence over on drill pit? _____	
Cuttings management: _____			
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____			
Production areas have been stabilized? _____		Segregated soils have been replaced? _____	
<b>RESTORATION AND REVEGETATION</b>			
<u>Cropland</u>			
Top soil replaced _____		Recontoured _____	Perennial forage re-established _____
<u>Non-Cropland</u>			

Inspector Name: LONGWORTH, MIKE

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Gravel	Pass					
		Ditches	Pass			
		Compaction	Pass			
Berms	Pass					
Seeding	Pass					
		Culverts	Pass			
Compaction	Pass					

S/A/V: SATISFACTOR

Corrective Date: \_\_\_\_\_

Y

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
674702945	INSPECTION APPROVED	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3904446">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3904446</a>

