



Photo#1: Overview of Location from Entry to NW, showing Gravel Stock Piles at either end of Well Corral.

July 7, 2016

Inspection Photos: LINN Loc#335834



Photo#2: View East of Well Corral with Eight Conductor's set.

Inspection Photos: LINN Loc#335834

July 7, 2016





Photo#3: Gravel Stock Pile at West end of Well Corral. Cheat Grass establishing.

Inspection Photos: LINN Loc#335834

July 7, 2016



Photo#4: It appears Controls have been applied to Noxious Weed population on Location.

Inspection Photos: LINN Loc#335834

July 7, 2016





Photo#5: Drainage between Two Vegetated berms leading to Sediment Trap

Inspection Photos: LINN Loc#335834

July 7, 2016



Photo#6: View of Well Vegetated Berm on South Side of Location.

Inspection Photos: LINN Loc#335834

July 7, 2016