



Photo#1: Entry Sign

July 7, 2016

Inspection Photos: LINN Loc#335865



Photo#2: View of Well Corral; Land Farming site directly in back indicated by arrow.

Inspection Photos: LINN Loc#335865

July 7, 2016



Photo#3: One Conductor Set on Location.

Inspection Photos: LINN Loc#335865

July 7, 2016





Photo#4: Well Vegetated Interim Rec Area.

Inspection Photos: LINN Loc#335865

July 7, 2016



Photo#5: Land Application Site; View to South.

Inspection Photos: LINN Loc#335865

July 7, 2016



Photo#6: View to West over Land Farming Area.

Inspection Photos: LINN Loc#335865

July 7, 2016