

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/20/2016

Document Number:

675203070

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	297855	334464	CONKLIN, CURTIS	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Bankert, Wayne	(970) 683-5419	wbankert@laramie-energy.com	Senior Regulatory & Environmental Coordinator

Compliance Summary:QtrQtr: NESE Sec: 22 Twp: 9S Range: 93W**Inspector Comment:**Wells have been previously inspected. Inspection to pass final reclamation for AL wells only.**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
297855	WELL	AL	05/18/2016	LO	077-09705	NVega 22-424	AL	<input checked="" type="checkbox"/>
297856	WELL	AL	05/18/2016	LO	077-09706	NVega 22-434	AL	<input checked="" type="checkbox"/>
297857	WELL	AL	05/18/2016	LO	077-09707	NVega 22-431	AL	<input checked="" type="checkbox"/>
297858	WELL	PR	04/03/2013	GW	077-09708	NVEGA 2C-22-433D	PR	<input type="checkbox"/>
299973	WELL	AL	05/18/2016	LO	077-09843	NVega 23-133	AL	<input checked="" type="checkbox"/>
299974	WELL	AL	05/18/2016	LO	077-09844	NVega 22-422	AL	<input checked="" type="checkbox"/>
299975	WELL	AL	05/18/2016	LO	077-09845	NVega 22-433	AL	<input checked="" type="checkbox"/>
299976	WELL	AL	05/18/2016	LO	077-09846	NVega 22-333	AL	<input checked="" type="checkbox"/>
299977	WELL	AL	05/18/2016	LO	077-09847	NVega 22-322	AL	<input checked="" type="checkbox"/>
299978	WELL	AL	05/18/2016	LO	077-09848	NVega 22-432	AL	<input checked="" type="checkbox"/>
299979	WELL	AL	05/18/2016	LO	077-09849	NVega 22-342	AL	<input checked="" type="checkbox"/>
299980	WELL	AL	05/18/2016	LO	077-09850	NVega 22-343	AL	<input checked="" type="checkbox"/>

Inspector Name: CONKLIN, CURTIS

299981	WELL	AL	05/18/2016	LO	077-09851	NVega 22-423	AL	<input checked="" type="checkbox"/>
299982	WELL	AL	05/18/2016	LO	077-09852	NVega 22-332	AL	<input checked="" type="checkbox"/>
299994	WELL	AL	05/18/2016	LO	077-09853	NVega 22-323	AL	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Emergency Contact Number (S/AR): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:

Type:	#	Satisfactory/Action Required:
Comment		
Corrective Action		Date: _____

Venting:

Yes/No

Comment	
---------	--

Flaring:

Type	Satisfactory/Action Required		
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 297855

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:**On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: <u>297855</u>	Type: <u>WELL</u>	API Number: <u>077-09705</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>297856</u>	Type: <u>WELL</u>	API Number: <u>077-09706</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>297857</u>	Type: <u>WELL</u>	API Number: <u>077-09707</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>

Inspector Name: CONKLIN, CURTIS

Facility ID:	299973	Type:	WELL	API Number:	077-09843	Status:	AL	Insp. Status:	AL
Facility ID:	299974	Type:	WELL	API Number:	077-09844	Status:	AL	Insp. Status:	AL
Facility ID:	299975	Type:	WELL	API Number:	077-09845	Status:	AL	Insp. Status:	AL
Facility ID:	299976	Type:	WELL	API Number:	077-09846	Status:	AL	Insp. Status:	AL
Facility ID:	299977	Type:	WELL	API Number:	077-09847	Status:	AL	Insp. Status:	AL
Facility ID:	299978	Type:	WELL	API Number:	077-09848	Status:	AL	Insp. Status:	AL
Facility ID:	299979	Type:	WELL	API Number:	077-09849	Status:	AL	Insp. Status:	AL
Facility ID:	299980	Type:	WELL	API Number:	077-09850	Status:	AL	Insp. Status:	AL
Facility ID:	299981	Type:	WELL	API Number:	077-09851	Status:	AL	Insp. Status:	AL
Facility ID:	299982	Type:	WELL	API Number:	077-09852	Status:	AL	Insp. Status:	AL
Facility ID:	299994	Type:	WELL	API Number:	077-09853	Status:	AL	Insp. Status:	AL

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment:
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location:

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____

CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____

CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____

CA Date _____

Guy line anchors marked? _____

CM _____

CA _____

CA Date _____

1003b. Area no longer in use? _____

Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Inspector Name: CONKLIN, CURTIS

Comment:

Corrective Action:

Date

Overall Final Reclamation ☐ Pass

Well Release on Active Location ☐

Multi-Well Location ☒

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
------------------	-----------------	-------------------------	-----------------------	---------------	--------------------------	---------

S/A/V: _____ Corrective Date: _____

Comment:

CA:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203070	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3908492