



Photo#1: Project Entry view to West



## Dirt work has commenced on some sections of Project

**Photo#2 June 16,2016**



**Photo#3 July 19,2016**



July 19, 2016

Inspection Photos: Grynberg -Chivington 1 - 081-05709 (7-19-16)



SW ditch has been installed around Project Area.

**Photo#4: View South side of Location.**



**Photo#5: View North side of Location**





Photo#6: View of SW Ditch intersects with Entry Road ; where BMPs need to be installed.

Inspection Photos: Grynberg -Chivington 1 - 081-05709 (7-19-16)

July 19, 2016



## Ditch termination points at Access Road

**Photo#7: North side of Access Road.**



**Photo#8: South side of Access Road.**





Photo#9: Weeds, predominately Halogeton are establishing on Site Disturbances.

Inspection Photos: Grynberg -Chivington 1 - 081-05709 (7-19-16)

July 19, 2016